

Standard Engineering Views

To get standard engineering views of your part (e.g. top, right, isometric, *etc.*), select **Tools** → **Standard Views**. You will get a separate toolbar that has buttons for the standard views.



Using this toolbar will make it easier to get the view of your part that you want. This toolbar is an add-on to IronCAD and does not behave like other toolbars. It's a nuisance sometimes, but the standard views are useful, so it's worth it to put up with it.